

Device affected	Package Code
ISP130603_IB	Hardware Revision F

Date (YYYY-MM-DD)	PAN number	Document version :
2020-06-26	ISP130603_IB_F_PAN	1.0

---

Change log

Version	Change #
<b>ISP130603_IB_F_PAN_v1.0</b>	<p><b>#1:</b> Power Supply to the module is now (Rev F) protected by a current limiting switch that is normally OFF when J22 is not shorted. Operation without this jumper is erratic as the module may be powered by a parasitic connection through diodes from the SWD interface.</p> <p>Corrective Action: Ensure that a jumper is placed on J22 to switch the current limiting switch on.</p> <p>All ISP DK App Notes describing use of the interface board will be updated to reflect the above.</p>

---