

Device affected	Package Code
ISP4520-EU	Rev C – Rev D
ISP4520-US	Rev A
ISP4520-JP	Rev A

Date (YYYY-MM-DD)	PAN number	Document version :
2019-05-02	ISP4520_C_PAN	1.0

PAN Description: Crosstalk between the SWD bus and BLE 32MHz XTAL

Version	PAN Description detailed
ISP4520_C_PAN_v1.0	Using the nRF52 debug system will prevent from correctly using the BLE Radio. Workaround: Stop the JLink connection before trying to establish a BLE connection with the module.