

## **Product Discontinuity Notice**

ISP091201 BN PDN v1.0

Device affected	Package code		
ISP091201-BN	All versions		

Date (YYYY-MM-DD)	PDN reference	Document version
2021-04-01	ISP091201_PDN	1.0

## **Reason for discontinuity**

Several components and materials required for module manufacturing are discontinued.

Last order date Last shipping date

2021-10-01 2022-04-01

## **Alternative solution for customer**

Re-design the application with newer module generation which are smaller and compliant for power supply and for integrated antenna design rules.

**Approvals** 

Quality Director: Date: Signature:

Chris Barratt 2021-04-01

Operation Manager: Date: Signature:

Philippe Genin 2021-04-01